


BEACH STREET

Beach St. -- Statement of Significance

Beach St. seems to have existed since shortly after the Civil War - for what purpose is unknown. It was uninhabited until housing pressures finally reached this far into the south end in the 1890's; the two homes on the north side of the street were built together, probably on speculation, in 1898. The two houses across the street were built in the 1920's. These houses were typical of the entire south end; solid but rather plain homes for moderate-income white collar workers.



STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Chittenden

TOWN: Burlington

LOCATION:
11 Beach St.

FUNCTIONAL TYPE: dwelling

COMMON NAME:

OWNER: Francis & Dorothy Mackin

ADDRESS: 11 Beach St.
Burlington

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

DATE BUILT: 1925

GENERAL DESCRIPTION:

Structural System

rockfaced

1. Foundation: Brick Stone Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 - c. Iron
 - d. Steel
 - e. Other:
3. Wall Covering: Clapboard Wood Shingle Board & Batten Shiplap Novelty Stucco Tile Brick Stone Slate Sheet Metal Asphalt Shingle Aluminum
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other: rafter
5. Roof Covering: Wood Shingle Asphalt Shingle Tile Slate Sheet Metal Paper Built Up Rolled
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Dormers Bay Windows Ells Chimneys Cupolas Wings Sheds Other:

Number of Stories: 2 1/2 Number of Bays: 2 x 2 Entrance Location: side hall
Approximate Dimensions:

Roof Style: Gable Gambrel Flat Shed Hip Mansard Jerkinhead Monitor Saw Tooth Other:
With Belcast With Parapet With False Front

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Other:

SURVEY NUMBER:

11 Beach St.

NEGATIVE FILE NUMBER:

77-A-503

LATITUDE:

LONGITUDE:

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

Mackin house

ORIGINAL FORMAL NAME:

G. McLeod house

PRESENT USE: residence

ORIGINAL USE: same

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Deteriorated

THEME:

STYLE: Colonial Revival

LOCAL ATTITUDES:
Positive <input type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/>
Other: <input type="checkbox"/>

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Massing - rectangular block, hip roof, dormer east elev., pedimented front porch, rear, shed-roofed entranceway.

Fenestration - paired & triple windows with upper sash divided vertically into 4 sections. Plain surrounds with strip molded heads.

Door - plain surround, strip molded head. Oak door with long glass panel.

Enrichments - exterior chimney, shingled upper floor dormer with slate clad walls.

RELATED STRUCTURES:


Flat roofed garage, shiplap sided.

STATEMENT OF SIGNIFICANCE:

Built in 1925. This typical Colonial Revival house and the house next door of the same date, utilize rockfaced concrete block. The combination of wide, tinted, mortar joints and the rockfaced concrete block gives an excellent simulation of a stone foundation. The first occupant was George McLeod, a commercial traveler.

REFERENCES:

Sanborn Maps, City Directories

MAP: (Indicate North In Circle)**SURROUNDING ENVIRONMENT:**


- Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Other: _____

RECORDED BY:

Adele Cramer

ORGANIZATION:
VT Division for Historic Preservation**DATE RECORDED:**

8/23/77



STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY:	Chittenden
TOWN:	Burlington
LOCATION:	14 Beach St.
FUNCTIONAL TYPE:	dwelling
COMMON NAME:	
OWNER:	Donald & Gail Steffens
ADDRESS:	14 Beach St. Burlington
ACCESSIBILITY TO PUBLIC:	 Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Restricted <input type="checkbox"/>
LEVEL OF SIGNIFICANCE:	 Local <input checked="" type="checkbox"/> State <input checked="" type="checkbox"/> National <input type="checkbox"/>
DATE BUILT:	ca. 1898

GENERAL DESCRIPTION:

- structural system

 1. Foundation: Brick Stone Concrete Concrete Block
 2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron
 - d. Steel
 - e. Other: _____
 3. Wall Covering: Clapboard Wood Shingle Board & Batten
Shiplap Novelty Stucco Tile Brick Stone
Slate Sheet Metal Asphalt Shingle Aluminum
 4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other: rafter _____
 5. Roof Covering: Wood Shingle Asphalt Shingle Tile
Slate Sheet Metal Paper Built Up Rolled
 6. Engineering Structure:
 7. Other: _____

Appendages: Porches ■ Towers ■ Dormers ■ Bay Windows ■ Ells ■
Chimneys ■ Cupolas ■ Wings ■ Sheds ■ Other:

Number of Stories: 1 1/2 Number of Bays: 2 x 2 Entrance Location: recessed
Approximate Dimensions: _____ in lot bay

Roof Style: Gable Gambrel Flat Shed Hip Mansard
Jerkinhead Monitor Saw Tooth Other: _____

Jerkinthead Monitor Saw Tooth Other:
With Belcast With Paragnet With False Eye

With Belcast With Parapet With False

CREATE EG STRUCTURE **GLOBAL ATTENTIVES**

THREAT TO STRUCTURE:			
<input type="checkbox"/> No Threat	<input type="checkbox"/> Zoning	<input type="checkbox"/> Roads	<input type="checkbox"/>
<input type="checkbox"/> Development	<input type="checkbox"/> Deterioration	<input type="checkbox"/>	<input type="checkbox"/>
Other:			

SURVEY NUMBER:		14 Beach St.
NEGATIVE FILE NUMBER:		77-A-503
LATITUDE	LONGITUDE	
U.S.G.S. QUAD. MAP:		
PRESENT FORMAL NAME: Steffens house		
ORIGINAL FORMAL NAME: Luke Hall house		
PRESENT USE: residence		
ORIGINAL USE: same		
ARCHITECT/ENGINEER:		
BUILDER/CONTRACTOR:		
PHYSICAL CONDITION OF STRUCTURE:		
Excellent <input checked="" type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/>		
THEME:		
STYLE:		
<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Concrete Block <input type="checkbox"/>		
Western Platform <input type="checkbox"/> Post & Beam <input type="checkbox"/> Brick <input checked="" type="checkbox"/> Stone <input type="checkbox"/> Concrete <input type="checkbox"/>		
<input type="checkbox"/> Wood Shingle <input type="checkbox"/> Board & Batten <input type="checkbox"/> Tucco <input type="checkbox"/> Tile <input type="checkbox"/> Brick <input type="checkbox"/> Stone <input type="checkbox"/> Asphalt Shingle <input type="checkbox"/> Aluminum <input type="checkbox"/> Asbestos Shingle <input type="checkbox"/> Steel <input type="checkbox"/> Concrete <input type="checkbox"/> <input type="checkbox"/> Concrete <input type="checkbox"/>		
Shingle <input type="checkbox"/> Asphalt Shingle <input type="checkbox"/> Tile <input type="checkbox"/> Paper <input type="checkbox"/> Built Up <input type="checkbox"/> Rolled <input type="checkbox"/>		
Dormers <input type="checkbox"/> Bay Windows <input type="checkbox"/> Ellis <input type="checkbox"/> Sheds <input type="checkbox"/> Other:		
Bays: 2 x 2 Entrance Location: recessed in 1st bay		
Flat <input type="checkbox"/> Shed <input type="checkbox"/> Hip <input type="checkbox"/> Mansard <input type="checkbox"/> ooth <input type="checkbox"/> Other: With False Front <input type="checkbox"/>		
LOCAL ATTITUDES:		
Positive <input type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:		

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Massing - gable roofed section with one bellcast eave. Other slope extends beyond the 1st floor and arches into the wall to incorporate a front porch. In front of the main block is attached a hip & roofed tower-like projection. Rear porch.

Fenestration - 12 over 1 sashes. A long, narrow window with 16 panes and 9 over 1 sashes is located on the east elevation and lights the interior stairway.

Door - molded surround

Cornice - hip roofed section has exposed rafter tails.

RELATED STRUCTURES: shingled garage with double doors on hinges. Doors are flush boarded with criss-crossed boards on top of the flush boards.


STATEMENT OF SIGNIFICANCE:

This shingled house with rooflines of various slopes and curves, is similar to houses on upper Howard St. and were probably constructed by the same builder, and were probably also part of the Henderson and Gay development plan. The first resident here was Luke W. Hall, piano tuner at Bailey's Music rooms.

REFERENCES:

Sanborn Maps, City Directories

MAP: (Indicate North In Circle)

**SURROUNDING ENVIRONMENT:**

- Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Other:

RECORDED BY:

Adele Cramer

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

8/23/77

STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Chittenden

TOWN: Burlington

LOCATION:
15 Beach St.

FUNCTIONAL TYPE: dwelling

COMMON NAME:

OWNER: Myrtle Harrison Wishart, J. &
ADDRESS: Margaret Kemp
15 Beach St., Burlington

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

DATE BUILT: ca. 1925

GENERAL DESCRIPTION:

Structural System

rockfaced

1. Foundation: Brick Stone Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron
 - d. Steel
 - e. Other: _____
3. Wall Covering: Clapboard Wood Shingle Board & Batten
Shiplap Novelty Stucco Tile Brick Stone
Slate Sheet Metal Asphalt Shingle Aluminum
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other: rafter _____
5. Roof Covering: Wood Shingle Asphalt Shingle Tile
Slate Sheet Metal Paper Built Up Rolled
6. Engineering Structure:
7. Other: _____

Appendages: Porches Towers Dormers Bay Windows Ells
Chimneys Cupolas Wings Sheds Other: _____

Number of Stories: 2 1/2 Number of Bays: 2 x 2 Entrance Location: side hall
Approximate Dimensions:

Roof Style: Gable Gambrel Flat Shed Hip Mansard
Jerkinhead Monitor Saw Tooth Other:
With Belcast With Parapet With False Front

THREAT TO STRUCTURE:

No Threat Zoning Roads

Development Deterioration

Other: _____

SURVEY NUMBER: 15 Beach St.

NEGATIVE FILE NUMBER: 77-A-503

LATITUDE LONGITUDE

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:
H. Wishart house

PRESENT USE: Residence

ORIGINAL USE: Same

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good
Fair Deteriorated

THEME:

STYLE: Colonial Revival

LOCAL ATTITUDES:

Positive Negative Mixed

Other: _____

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

- Massing - rectangular block with 2-bay, shed roofed front porch.
- Fenestration - double & triple windows front elevation 6 over 1 sashes. Plain surrounds, strip molded heads.
- Door - plain surround, strip-molded head. Treblated glass panel in oak door.
- Enrichments - shingled upper floor


RELATED STRUCTURES:**STATEMENT OF SIGNIFICANCE:**

The outstanding feature of this otherwise typical Colonial Revival house is its use of rockfaced concrete block and wide tinted mortar joints to simulate the look of stone. First occupant was Harry R. Wishart, teller for the Chittenden Trust Co.

REFERENCES:

- Sanborns Maps, City Directories

MAP: (Indicate North In Circle)

**SURROUNDING ENVIRONMENT:**

- Open Land Woodland
- Scattered Buildings
- Moderately Built Up
- Densely Built Up
- Residential Commercial
- Agricultural Industrial
- Other:

RECORDED BY:

Adele Cramer

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

8/23/77

STATE OF VERMONT
Division of Historic Sites
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

COUNTY: Chittenden

TOWN: Burlington

LOCATION:
18 Beach St.

FUNCTIONAL TYPE: dwelling

COMMON NAME:

OWNER: Earl & Marion Hulburd

ADDRESS: 18 Beach St.
Burlington

ACCESSIBILITY TO PUBLIC:

Yes No Restricted

LEVEL OF SIGNIFICANCE:

Local State National

DATE BUILT: 1899

GENERAL DESCRIPTION:

Structural System

1. Foundation: Brick Stone Concrete Concrete Block
2. Wall Structure
 - a. Wood Frame: Balloon Western Platform Post & Beam
 - b. Load Bearing Masonry: Brick Stone Concrete
Concrete Block
 - c. Iron
 - d. Steel
 - e. Other:
3. Wall Covering: Clapboard Wood Shingle Board & Batten
Shiplap Novelty Stucco Tile Brick Stone
Slate Sheet Metal Asphalt Shingle Aluminum asbestos
4. Roof Structure
 - a. Truss: Wood Iron Steel Concrete
 - b. Vault: Brick Stone Concrete
 - c. Other: rafter
5. Roof Covering: Wood Shingle Asphalt Shingle Tile
Slate Sheet Metal Paper Built Up Rolled
6. Engineering Structure:
7. Other:

Appendages: Porches Towers Dormers Bay Windows Ells
Chimneys Cupolas Wings Sheds Other:

Number of Stories: 1 1/2 Number of Bays: 2 x 2 Entrance Location: side of front gabled section

Approximate Dimensions:

Roof Style: Gable Gambrel Flat Shed Hip Mansard
Jerkinhead Monitor Saw Tooth Other:
With Belcast With Parapet With False Front

THREAT TO STRUCTURE:

No Threat Zoning Roads
Development Deterioration
Other:

SURVEY NUMBER:

18 Beach St.

NEGATIVE FILE NUMBER:

77-A-503

LATITUDE

LONGITUDE

U.S.G.S. QUAD. MAP:

PRESENT FORMAL NAME:

Hulburd house

ORIGINAL FORMAL NAME:

H. Leach house

PRESENT USE: residence

ORIGINAL USE: same

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent Good

Fair Deteriorated

THEME:

STYLE:

LOCAL ATTITUDES:

Positive Negative Mixed
Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Massing - front gable orientation. One slope of the gable is extended to the 1st floor level. Rising from this slope is a hip-roofed wall dormer. Other slope overhangs the east wall which is curved to meet the cornice. Front porch recessed but with a narrow bellcast hip roof supported on columns. Enclosed rear porches both floors.

Fenestration - 12 over 1 and 9 over 1 sashes. Long narrow window, 16 panes, east elevation which lights stairway.

Door - plain surround

Cornice - overhang sections with exposed rafter tails.

RELATED STRUCTURES:


SHIPLAP SIDED GARAGE, OVERHEAD DOOR

STATEMENT OF SIGNIFICANCE:

Similar in style to 14 Beach and houses behind it on Howard St. This house was probably part of the Henderson and Gay development plan and were indoubtably constructed by the same builder. Home of Horatio N. Leach, cashier for the Rutland R. R. freight house.

REFERENCES:

Sanborn Maps, City Directories.

MAP: (Indicate North In Circle)**SURROUNDING ENVIRONMENT:**

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Other: _____

RECORDED BY:

Adele Cramer

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

8/23/77