CHASE LANE Burlington



	SURVEY NUMBER:	
	NEGATIVE FILE NUMBER: 78-A-287	
	UTM REFERENCES:	
c Preservation Montpelier, VI 05002	Zone/Easting/Northing	
	U.S.G.S. QUAD. MAP:	
HISTORIC SITES & STRUCTURES SURVEY Individual Structure Survey Form		
	PRESENT FORMAL NAME:	
COUNTY: Chittenden	ORIGINAL FORMAL NAME:	
rown: Burlington	PRESENT USE: twin house	
LOCATION:	ORIGINAL USE: twin house	
6-8 Chase Lane	ARCHITECT/ENGINEER:	
COMMON NAME:		
	BUILDER/CONTRACTOR:	
FUNCTIONAL TYPE: dwelling		
OWNER: Mrs. S. R. Carter	PHYSICAL CONDITION OF STRUCTURE:	
ADDRESS: 8 Chase Lane	Excellent Good	
	Fair Poor	
ACCESSIBILITY TO PUBLIC:	STYLE: Queen Anne	
Yes No Restricted LEVEL OF SIGNIFICANCE:	DATE BUILT:	
Local State National	c. 1909	
GENERAL DESCRIPTION:		
Structural System		
1. Foundation: Stone Brick	Concrete Concrete Block	
2. Wall Structure		
a. Wood Frame: Post & Bea	m Balloon	
b. Load Bearing Masonry: Brick Stone Concrete		
Concrete Block		
c. Iron d. Steel e.	Other: Board & Batten Wood Shingle	
3. Wall Covering: Clapboard	Board & Batten wood Sningie	
ShiplapLi Novelty Li Asc	Destos Shingle Sheet Metal Stone Veneer	
Aluminum Asphalt Shingle Brick Veneer Stone Veneer Bonding Pattern: Common Other:		
Bonding Pattern: common 4. Roof Structure	Other.	
a. Truss: Wood Iron	Steel Concrete	
h Other.		
5. Roof Covering: Slate Wo	ood Shingle□ Asphalt Shingle□	
Sheet Metal Built Up Rolled Tile Other:		
6. Engineering Structure:		
7. Other:	unolac Dormers Chimneys	
Appendages: Porches Towers C	odow Other:	
Sheds Ells Wings Bay Wir Roof Style: Gable Hip Shed Jerkinhead Saw Tooth With M	Flat Mansard Gambrel	
Jerkinhead Saw Tooth With M	Monitor With Bellcast □	
With Parapet□ With False Front	Other:	
Number of Stories: 21		
Number of Bays:	Entrance Location: center	
Approximate Dimensions:		
THREAT TO STRUCTURE:	LOCAL ATTITUDES:	
No Threat Zoning Roads Development Deterioration	Positive Negative	
Development□ Deterioration□	Mixed Other:	
Alteration Other:		

ADDITIONAL ARCHITECTURAL OR STRUCTUR	AL DESCRIPTION:	
Massing - Rectangular block with 2 story of	corner bay windows on facade ter-	
elevation wings. Boxed cornice.		
Fenestration - 1/1 sash. Rowlock arches. Entrance - Two doors Queen Anne with squar	e light.	
Enrichments - Turned posts, brackets & fas in bay window pediments.	cia board canted butt shingles as	
RELATED STRUCTURES: (Describe) Ital	ianate barn stone foundation. For-	
eaves. Wall dormers. Cupola with open ro	ar block. Gable roof, projecting	
nices 6/6 sash. Clapboarded. Brackets at	eaves and corners.	
STATEMENT OF SIGNIFICANCE:		
This house was built c. 1909 as part of the subdivision of the yard of #21 Chase St., then owned by H. E. Sibley. It was undoubtably intended to serve as housing for mill workers.		
REFERENCES:		
Sanborns, directories.		
MAP: (Indicate North in Circle)	SURROUNDING ENVIRONMENT: Open Land Woodland	
	Scattered Buildings	
	Moderately Built Up ∭ Densely Built Up□	
	Residential Commercial	
	Agricultural Industrial Roadside Strip Development	
	Other:	
	RECORDED BY: C. R. Morsbach	
	CRGANIZATION: VT. Div. for Historic Preservation	
	DATE RECORDED:	
	10/22/78	



	SURVEY NUMBER:	
	NEGATIVE FILE NUMBER: 78-A-287	
OF VERMONT	UTM REFERENCES:	
on for Historic Preservation Montpelier, VT 05602	Zone/Easting/Northing	
HISTORIC SITES & STRUCTURES SURVEY	U.S.G.S. OUAD. MAP:	
Individual Structure Survey Form		
	PRESENT FORMAL NAME:	
COUNTY: Chittenden	ORIGINAL FORMAL NAME:	
TOWN: Burlington		
LOCATION:	PRESENT USE:	
9 ½ Chase Lane	ORIGINAL USE:	
onuse hance	ARCHITECT/ENGINEER:	
COMMON NAME:	BUILDER/CONTRACTOR:	
FUNCTIONAL TYPE: shop		
OWNER: Howard Morse	PHYSICAL CONDITION OF STRUCTURE:	
	Excellent Good G	
ADDRESS: 9 Chase Lane	Fair Poor	
ACCESSIBILITY TO PUBLIC:		
Yes No Restricted	STYLE: Italianate Commercial	
LEVEL OF SIGNIFICANCE:	DATE BUILT:	
Local State National	c. 1909	
GENERAL DESCRIPTION:		
Structural System		
1. Foundation: Stone Brick	☐ Concrete ☐ Concrete Block ☐	
2. Wall Structure		
a. Wood Frame: Post & Bea	m Balloon 🕷	
	Brick□ Stone□ Concrete□	
c. Iron□ d. Steel□ e.	Other:	
	Board & Batten Wood Shingle	
Shinlan Novelty Ash	estos Shingle Sheet Metal	
Aliminum [Achalt Shing	le Brick Veneer Stone Veneer	
Bonding Dottorn	Othor:	
Bonding Pattern: 4. Roof Structure	Oulier.	
a. Truss: Wood Iron	Stapil Concrete [
b. Other:	Decement Concrete Education	
5. Roof Covering: Slate Wood Shingle Asphalt Shingle		
Sheet Metal Built Up	Dollad Mila Cl. Othor.	
sneer metar burit up	KOTTEG OCHET	
6. Engineering Structure:		
7. Other:		
Appendages: Porches Towers C	upolas Dormers Chimneys	
Sheds Ells Wings Bay Win	dowOther:	
Roof Style: Gable Hip Shed	Flat Mansard Gambrel	
Jerkinhead	Mith Bellcast	
With Parapet With False Front	Other:	
Number of Stories: 1		
Number of Bays: 3 x 3	Entrance Location: center	
Approximate Dimensions:		
The prosecution of the property of the propert		
THREAT TO STRUCTURE:	LOCAL ATTITUDES:	
No Threat ☐ Zoning ☐ Roads ☐	Positive Negative	
Dorrolanmont C Dottomic action C	Mixed □ Other:	
· · · · · · · · · · · · · · · · · · ·	FILACULI OCHEL:	
Alteration Other:		

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:		
Massing - Rectangular block with shed on a gable roof. Boxed cornice.		
Fenestration - 2/2 sash. Shingled spandre Entrance - Double, multipaneled doors. Enrichments - Imbricated shingles. Bracket		
RELATED STRUCTURES: (Describe)		
STATEMENT OF SIGNIFICANCE:		
This house was apparantly constructed c. 1909. Chase Lane is essentially the subdivided yard of #21 Chase St., which was the elegant home of E. W. Chase and H. E. Sibley for many years. The subdivision took place a year or two before Sibley's death in 1910. The mills at Winooski Falls were then at a profitable moment, and this generated a need for increased housing for additional workers.		
REFERENCES:		
1890, Sanborn maps; directories.		
MAP: (Indicate North in Circle)	SURROUNDING ENVIRONMENT:	
	Open Land Woodland Scattered Buildings	
	Moderately Built Up	
	Residential Commercial Agricultural Industrial	
	Roadside Strip Development	
	RECORDED BY: C. R. Morsbach	
	ORGANIZATION: VT. Div. for Historic Preservation	
	DATE RECORDED: 10/22/78	