# WILSON STREET Burlington

#### NORTH BURLINGTON:

(Berry Street, Bright Street, Canfield Street, Charles Street Crowley Street, Derway Drive, Germain Street, Lakeview Terrace, Luck Street, Myrtle Street, Oak Street, Pomeroy Street, Poplar Street, Sherman Street, St. Louis Street, Staniford Road, Washington Street, Ward Street, Willow Street, Wilson Street.)

As lakeside commercial activity centered on Burlington Bay, the north-eastern shores of Lake Champlain remained undeveloped except for the few farms which took advantage of the rich Winooski River Valley soil. Family's such as the Derways, Stanifords and Crockers owned large acreage in far north Burlington from the latter 18th century well into the 19th century. A few structures exist from the late 1800's farms (#148, 240 Staniford Road) but only one is extant from the early 19th century, a Greek Revival style house (c.1820) near Appletree Point, an extension of the early Staniford Farm. This property was always used for farming, as was much of north Burlington, until the 1920's when lots were sectioned for suburban development and summer camps.

North Avenue, the highway connecting the far north farmlands with north Burlington, experienced the most architectural growth during the 19th century, especially after the completion of the trolley line in 1888. As lakeside factory development increased, so did the housing need for the immigrant French Canadian, Irish, and German workers. Outside of downtown Burlington and east, into the available farm land, streets such as Ward, Crowley, Washington and Strong began to fill lots with vernacular Queen Anne style housing. The ethnic neighborhoods maintained a cultural bond among their residents, with the establishment of community centers such as the Goethe Lodge (c.1891) on Crowley Street. The hall built by the German contractor, Oscar Heininger for his laborers and friends, operates as a club today.

Though not as isolated as the far northern sections of Burlington, the area north of Pearl Street was sparsely settled with farm houses into the late 1800's. Eventually parcels of land were sold to create Pomeroy, Germain and Wilson Streets, which came from Pomeroy, Dodge and Loomis farmland. The Shaw family sold their land to create Willow, Oak and Walnut Streets. Architectural development was greatest from the 1890's to 1920, but continued well into the 1930's and 1940's on most of these north end streets.

Across North Avenue on the lakeside, property purchased by the Vermont Central Railroad in the 1860's was sold to local north end contractors, such as the Kieslich's, Heininger's and Hauke's. Lakeview Terrace (known previously as the Bissell Street until the 1890's) had a few late 19th century houses scattered on a hill above the lake (#37, 131, 134 Lakeview Terrace.) By 1906, the Kieslich Construction Company had established a lumber warehouse and a model house at the south end of the street near Haswell and Canfield Streets (#71-73 Lakeview Terrace.) Housing growth continued north on Lakeview Terrace during the 1920's - 1940's going around the corner to Berry Street. Except for Sunset Court, a small 1940's deadend street a block north, only the Lakeview Terrace neighborhood commands a residential view of the lake in north Burlington. Later into the 1950's and 1960's the far north end would take advantage of the lake's vista for suburban housing.

NORTH BURLINGTON PAGE 2

Building in north Burlington during the twentieth century is checkered as new development is scattered between existing 19th century structures. It was the far north end where entire neighborhoods could by developed on the open farmlands and where planned development continues today.

Surveyor: Karen Czaikowski

Date: August 1983





STATE OF VERMONT
Division for Historic Preservation
Montpelier, VT 05602
UTM REFERENCES:
Zone/Easting/Northing

Montpelier, VT 05602	18/643120/4927030
HISTORIC SITES & STRUCTURES SURVEY	
Individual Structure Survey Form	U.S.G.S. QUAD. MAP: Burlington 7.5
	PRESENT FORMAL NAME: James Pembroke House
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington	Joseph Irwin House
LOCATION: 17 Wilson Street, Four lots	PRESENT USE: House
west from corner of Mansfield	ORIGINAL USE:
Street.	ARCHITECT/ENGINEER:
COMMON NAME:	Unknown
	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: House	Unknown
OWNER: James & Paula Pembroke	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: 17 Wilson Street	Excellent 🗆 Good 🜌
Burlington, VT 05401	Fair Poor
ACCESSIBILITY TO PUBLIC:	
Yes□ No Restricted□	STYLE: Vernacular
LEVEL OF SIGNIFICANCE:	DATE BUILT:
Local State National	1925
GENERAL DESCRIPTION:	
Structural System	
	Concrete Concrete Block
2. Wall Structure	
a. Wood Frame: Post & Bear	n Balloon
b. Load Bearing Masonry: 1	
Concrete Block	January Decision Control Com
c. Iron ☐ d. Steel ☐ e.	Othor
	Board & Batten [] Wood Shingle
3	estos Shingle Sheet Metal
	le  Brick Veneer Stone Veneer
Bonding Pattern:	Other:
4. Roof Structure	Other.
a. Truss: Wood Iron	Stool Congrete [
b. Other:	
5. Roof Covering: Slate Woo	od Shingle Asphalt Shingle
sneet Metal Built Up	Rolled Tile Other:
6. Engineering Structure:	
7. Other:	4.00000
Appendages: Porches Towers C	upolas Dormer Mar Chimney Mar
Sheds Ells Wings Bay Wind	dow Other:
Roof Style: Gable Hip Shed	Flat Mansard Gambrel
Jerkinhead☐ Saw Tooth☐ With Mo	onitor  With Bellcast
With Parapet With False Front	Other:
Number of Stories: 21	
Number of Bays: 2 x 2	Entrance Location: Front left
Approximate Dimensions: 20 x 20	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat Zoning Roads	Positive Negative
Development Deterioration	Mixed Other:
Alteration Other:	PITACULI OUNCE:
The state of the s	

SURVEY NUMBER:

FILE NUMBER:

# ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Two and one half story, Four-Square house with corner boards and water table first story clapboard with frieze and projecting box cornice. Center hip roof dormer with projecting box cornice, cornerboards and 3/1 sash windows. Second story of shingles. Front porch with battered columns rock-face concrete block piers, square-spindle railing, trellis skirt and pedimented cornice over entrance. Original front paneled door with large 3/4 length windows. Large tripartite window on first story with central pane, transom and 3/1 windows. 3/1 sash windows with lip molded lintels and plain surrounds.

RELATED STRUCTURES: (Describe)


Hip asphalt roof, clapboard single bay garage with altered overhead door (c.1925) (8'  $\times$  10').

## STATEMENT OF SIGNIFICANCE:

Wilson Street began its suburban development in the late 1800's on Dodge family farmland. It continued to develop into the 1920's when this well-preserved structure was built. This is a good example of the shingled, clapboarded 4-square type, and is the best preserved example on Wilson Street

REFERENCES:

Burlington Directory, 1925.







STATE OF VERMONT	OTM REFERENCES:
Division for Historic Preservation	Zone/Easting/Northing
Montpelier, VT 05602	18/643130/4927030
HISTORIC SITES & STRUCTURES SURVEY Individual Structure Survey Form	USSIC S. QUAD. MAP:
	PRESENT FORMAL NAME: William Neilson House
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington	103.03.774.200 2 02.02.200 272.02
LOCATION: 25 Wilson Street. Three lots	PRESENT USE: House
west from corner of Mansfield	ORIGINAL USE:
Avenue.	ARCHITECT/ENGINEER:
COMMON NAME:	Unknown
	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: House	Unknown
OWNER: William & Katharine Meilcon	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: 25 Wilson Street	Excellent 🗆 Good 🐷
Burlington VT 05401	Fair Poor
Burlington, VT 05401 ACCESSIBILITY TO PUBLIC:	
Yes No Restricted	STYLE: Vernacular
LEVEL OF SIGNIFICANCE:	DATE BUILT:
Local State National	1890
GENERAL DESCRIPTION:	
Structural System	
1. Foundation: Stone Brick	☐ Concrete ☐ Concrete Block ☐
2. Wall Structure	
a. Wood Frame: Post & Bear	
	Brick□ Stone□ Concrete□
Concrete Block□	
c. Iron□ d. Steel□ e.	
3. Wall Covering: Clapboard	Board & Batten D Wood Shingle
Shiplap∐ Novelty∐ Asb	estos Shingle Sheet Metal
Aluminum Asphalt Shing	le
Bonding Pattern:	Other:
4. Roof Structure	,
a. Truss: Wood Iron	Steel Concrete
b. Other:	
5. Roof Covering: Slate Wood Shingle Asphalt Shingle Sheet Metal Built Up Rolled Tile Other:	
Sneet metal   Built Up	KOILED Tile Other:
6. Engineering Structure: 7. Other:	exemple of the Benchmark of the contribution
Appendages: Porches Towers C	unalad Darmana Chimnaud
Sheds Ells Wings Bay Win	dow   Others   Chimney > ***
Roof Style: Gable Hip Shed	Flat Mansard Gambrel
Jerkinhead Saw Tooth With M	onitor With Bellcast
With Parapet With False Front	Other.
Number of Stories: 2½	a Contact .
Number of Bays: 2 x 3	Entrance Location: Ell right
Approximate Dimensions: 20 x 24	micronice modacion. Ell, right
LI ZU A ZH	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat  Zoning Roads	Positive Negative
Development Deterioration	Mixed □ Other:
Alteration Other:	
	&

SURVEY NUMBER:

0402 NEGATIVE FILE NUMBER: 83-A-112

# ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Two and one half story gable front L-plan house with west side ell entrance and altered porch (posts removed). Projecting box cornice, corner and water table. Full pedimented gable with decorative bands of shingles and 1/1 sash windows and plain surrounds with lip molded lintel. Rear enclosed porch with turned posts, shingled apron and rear 1 story shed. Interior center front chimney.

RELATED STRUCTURES: (Describe)

Gable end asphalt roof, clapboard garage with double track doors (c.1890) (14' x 12').

### STATEMENT OF SIGNIFICANCE:

This well-preserved house, built on what was initially called Dodge Street after the Dodge family farm land, exemplifies the rural development of eastern Burlington in the later 19th century. This typical "tri-gabled ell" dwelling, seen often in Burlington, is the only one on Wilson Street.

#### REFERENCES:

Chittenden County Historical Society Bulletin, July 1981.

