

ALLEN STREET

See photo in Elmwood Avenue forms.

STATE OF VERMONT  
 Division for Historic Preservation  
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY  
 District  Complex  Survey Form

SURVEY NUMBER:
NEGATIVE FILE NUMBER(S): 78-A-311
UTM REFERENCES: Zone/Easting/Northing A B C D
U.S.G.S. QUAD. MAP:

COUNTY: Chittenden
TOWN: Burlington
LOCATION: Allen & Elmwood Streets
NAME OF DISTRICT:
TYPE OF DISTRICT:
PHYSICAL CONDITION OF STRUCTURES: Excellent 100% Good % Fair % Poor %
LEVEL OF SIGNIFICANCE: Local <input checked="" type="checkbox"/> State <input type="checkbox"/> National <input type="checkbox"/>
THEMES:

COMPLEX INFORMATION ONLY
COMMON NAME: St. Joseph's Church & Rectory
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
TYPE OF COMPLEX: Church
TYPES OF STRUCTURES:
PRESENT USE: Church & rectory
ORIGINAL USE:" "
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
ACCESSIBILITY TO PUBLIC: Yes <input type="checkbox"/> No <input type="checkbox"/> Restricted <input checked="" type="checkbox"/>


**STATEMENT OF SIGNIFICANCE:**  
 The juxtaposition of these two buildings is interesting. The church, built in 1883 is Renaissance Revival characterized by such distinctive features as a pedimented pavilion and round arched masonry window and door openings. These openings are articulated by a lighter color limestone trim. The Rectory, built 21 years later has absorbed all the features of the Colonial Revival and yet relates quite well to the church by the use of similar masonry and accenting quoining and window trim.

St. Joseph's was built to replace a smaller, earlier St. Joseph's Church at the head of Archibald St. after the Civil War. Burlington grew rapidly as a consequence of the highly profitable lumber trade and industrialization in general. Thousands of workers, many of them French Canadian and Irish Catholic, moved to Burlington and settled in the North End. This new church was erected in 1883 to meet the needs of the growing parish. Its communicants were originally predominantly French speaking.


THREAT TO STRUCTURES: No Threat <input type="checkbox"/> Zoning <input type="checkbox"/> Roads <input type="checkbox"/> Development <input type="checkbox"/> Deterioration <input type="checkbox"/> Alteration <input type="checkbox"/> Other:
---

LOCAL ATTITUDES: Positive <input type="checkbox"/> Negative <input type="checkbox"/> Mixed <input type="checkbox"/> Other:
--

MAP: (1. Indicate NORTH in circle. 2. Represent each structure as an open box. 3. Number each structure inside of its box.)



PERU ST.



ALLEN ST.

ELMWOOD AVENUE

BOUNDARY DESCRIPTION:

REFERENCES:

RECORDED BY:  
C.R. Morsbach

ORGANIZATION:  
Vt. Div. for Historic Preservation

DATE RECORDED:  
11/1/78

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input checked="" type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER: 1	DATE BUILT: 1904	SURVEY NUMBER:
FUNCTIONAL TYPE: Rectory	NEGATIVE FILE NUMBER: 78-A-311	
COMMON NAME: St. Joseph's Rectory	OWNER:	
DESCRIPTION: <u>Style-</u> Colonial Revival <u>Massing:</u> Square block w/ attached wing. Main block 2½ storys, wing z. 2 story bay window on south elevation. Wood gazebo on north elevation and gallery that attaches to church. Hipped wall dormer on facade. Hip roofed dormers on south and north elevations. Veranda on south elevation of wing. Turned posts Entrance porch with fluted Ionic columns. Granite quoining articulates the corners. The window trim is also granite. The building is constructed of load bearing, rock faced ashlar that is randomly coursed. The roof is slate. Entire 1st floor walls and ceiling are pressed tin.		
MAP NUMBER: 2	DATE BUILT: 1883	SURVEY NUMBER:
FUNCTIONAL TYPE: Church	NEGATIVE FILE NUMBER: 78-A-311	
COMMON NAME: St. Josephs Church	OWNER:	
DESCRIPTION: <u>Style-</u> Renaissance Revival <u>Massing:</u> Rectangular block with attached mansard addition on rear. Main block is 3x8 bays constructed of random coursed, rock face ashlar masonry. Red slate roof. Facade is distinguished by pedimented pavillion. 2 section, drum steeple rises from square base. Windows and door openings above ground floor are arched with keystones. These openings are trimmed in limestone that contrasts with masonry walls. The quoins are also of limestone.		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER:	
DESCRIPTION:		

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/> COMPLEX <input type="checkbox"/>		
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		
MAP NUMBER:	DATE BUILT:	SURVEY NUMBER:
FUNCTIONAL TYPE:		NEGATIVE FILE NUMBER:
COMMON NAME:		OWNER:
DESCRIPTION:		