

PROCTOR PLACE

6 Proctor Place
is in Lakeside
Avenue Folder.

L.C.

11/26/80

OUTSTANDING COMPONENTS OF DISTRICT <input type="checkbox"/>		COMPLEX <input type="checkbox"/>
(Include individual survey number ONLY if surveyed individually.)		
MAP NUMBER:	DATE BUILT: ca 1925	SURVEY NUMBER: 93 Central
FUNCTIONAL TYPE: dwelling	NEGATIVE FILE NUMBER: 77-A-279	
COMMON NAME:	OWNER: R. and G. Poulin	
DESCRIPTION: Hipped roof Bungalow, 1 1/2 story, 3 x 3 bay, aluminum siding, asphalt shingle roof, concrete foundation. 6/1 sash windows. Front verandah, hipped roof front dormer.		
MAP NUMBER:	DATE BUILT: 1899	SURVEY NUMBER: 6 Proctor Place
FUNCTIONAL TYPE: dwelling	NEGATIVE FILE NUMBER:	
COMMON NAME:	OWNER: Lendor Masse	
DESCRIPTION: 1 1/2 story, 3 x 2 bay workers dwelling. Beautifully imbricated slate roof. Aluminum siding, 2/2 sash windows. Main facade orientation. Stone foundation.		
MAP NUMBER:	DATE BUILT: 1905	SURVEY NUMBER: 8 Conger Ave.
FUNCTIONAL TYPE: dwelling	NEGATIVE FILE NUMBER: 77-A-279	
COMMON NAME:	OWNER: Tim King	
DESCRIPTION: 2 1/2 story, 2 x 3 bay, framed house with steep pitched hipped roof. 1/1 sash windows. 1 story oriel window on facade with Queen Anne sashes of colored glass. Aluminum siding, slate roof, stone foundation. Porch with doric columns on N. W. corner. Box cornice with modillions. Hipped roof dormer with Queen Anne sash with colored glass.		
MAP NUMBER:	DATE BUILT: 1920	SURVEY NUMBER: 14-16 Conger Ave
FUNCTIONAL TYPE: dwelling	NEGATIVE FILE NUMBER: 77-A-279	
COMMON NAME:	OWNER: Laura Fay	
DESCRIPTION: Colonial Revival, 4 x 2 bay, 2 1/2 story framed house with 6/6 sash windows, wood shingle siding, slate roof, concrete foundation. Semi-circular fanlight in gable end, 2 inside chimneys on ridge. Box cornice with partial returns. 2 gabled entrance porches. Paired sash windows on 2 center bays.		