


CLYMER STREET



STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER: 11-15 Clymer
 NEGATIVE FILE NUMBER: 78-A-48
 UTM REFERENCES: Zone/Easting/Northing
 U.S.G.S. QUAD. MAP:
 PRESENT FORMAL NAME:
 ORIGINAL FORMAL NAME:
 PRESENT USE: tenement
 ORIGINAL USE: tenement
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 THEME:
 STYLE: Queen Anne - Colonial
 DATE BUILT: ca. 1898

COUNTY:
 TOWN:
 LOCATION:
 COMMON NAME:
 FUNCTIONAL TYPE: tenement
 OWNER: Winston J. Munson
 ADDRESS: Thayers Beach RFD 3 Holy Cross Rd. Winooski, 05404
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Stucco Sheet Metal Aluminum
 Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other: rafter
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 2 1/2
 Number of Bays: 8 x 2
 Approximate Dimensions: Entrance Location: at each end

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:


Rectangular block with main facade orientation. Entrance porches are located at each end of the facade. 2 centered inside chimneys along the roof ridge. 2/2 sash windows. Entablature type window head molding. Both entrances have similar surrounds as windows. Paneled colonial revival type door with top glazed. Each have garland & swags. Straight eaves. Porches are supported by Queen Anne posts with stick work elaboration in the post tops.

RELATED STRUCTURES: (Describe)**STATEMENT OF SIGNIFICANCE:**

Clymer Street was graded sometime in the late 1890's. At the turn of the century 4 families are listed on the street. Their occupation range from coachman to yardmaster for the Rutland R.R. It is likely that this tenement was one fo the first buildings on the street. It has several Colonial Revival features which would have been in style at the time (the doors and window heads) but the 2/2 windows mark it as workers housing. The similarities in detail to 21 Clymer St. seem to suggest that they were constructed at the same time.

REFERENCES:

City Directories

MAP: (Indicate North In Circle)**SURROUNDING ENVIRONMENT:**

Open Land Woodland
 Scattered Buildings
 Moderately Built Up
 Densely Built Up
 Residential Commercial
 Agricultural Industrial
 Roadside Strip Development
 Other:

RECORDED BY:

Clark Schuttle

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

11/22/77



Historic Preservation
Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
Individual Structure Survey Form

SURVEY NUMBER: 21 Clymer
 NEGATIVE FILE NUMBER: 70-A-13
 UTM REFERENCES: Zone/Easting/Northing
 U.S.G.S. QUAD. MAP:
 PRESENT FORMAL NAME:
 ORIGINAL FORMAL NAME:
 PRESENT USE: dwelling
 ORIGINAL USE: dwelling
 ARCHITECT/ENGINEER:
 BUILDER/CONTRACTOR:
 PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
 THEME:
 STYLE: Queen Anne - Colonial
 DATE BUILT: ca. 1898

COUNTY:
 TOWN:
 LOCATION:
 COMMON NAME:
 FUNCTIONAL TYPE: dwelling
 OWNER: Edward C. & Rita Papin
 ADDRESS: 21 Clymer St., Burlington
 ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
 LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete
 Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Stucco Sheet Metal Aluminum
 Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other:
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other: rafter
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 2
 Number of Bays: 2 x 3
 Approximate Dimensions: Entrance Location: on west side and in ell.

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:
 LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Main section is rectangular with front gable orientation. Slightly lower ell projects from the east side. A porch is at the juncture of the main section and ell. The entrance to the porch is at the corner. 2/2 sash windows in plain surrounds. Straight eaves. Fairly elaborate stick work in front gable end constructed out of standard mullied spindles etc. 2 doors each identical to the doors on 11-15 Clymer, but painted to highlight the Colonial Revival details.

RELATED STRUCTURES: (Describe)**STATEMENT OF SIGNIFICANCE:**

See 11-15 Clymer Street statement of Significance.
 Besides being one of the first houses on the street this house is further distinguished by its interesting entrance porch and elaborate stickwork in the gable end. These extraordinary details are not usually found on workers - style housing such as this.

REFERENCES:

City Directories

MAP: (Indicate North in Circle)**SURROUNDING ENVIRONMENT:**

Open Land Woodland
 Scattered Buildings
 Moderately Built Up
 Densely Built Up
 Residential Commercial
 Agricultural Industrial
 Roadside Strip Development
 Other:

RECORDED BY:

Clark Schuttle

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

11/22/77