JOHNSON STREET




OF VERMONT	UTM REFERENCES:
on for Historic Preservation	Zone/Easting/Northing
Montpelier, VT 05602	
HISTORIC SITES & STRUCTURES SURVEY	U.S.G.S. QUAD. MAP:
Individual Structure Survey Form	
	PRESENT FORMAL NAME:
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington	
LOCATION:	PRESENT USE: apartment
11-15 Johnson St.	ORIGINAL USE: apartment
11 15 oomson st.	ARCHITECT/ENGINEER:
COMMON NAME:	MICHTERET HWEINER.
COMMON MANUE.	BUILDER/CONTRACTOR:
THE VALCETT CARTA T. FORTATATA A	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: dwelling	
OWNER: B. & G. Corporation	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS:	Excellent Good Good
	Fair Poor _
ACCESSIBILITY TO PUBLIC:	
Yes No Restricted	STYLE: late Italianate
LEVEL OF SIGNIFICANCE:	DATE BUILT: c. 1889
Local State National	
GENERAL DESCRIPTION:	
Structural System	
1. Foundation: Stone Brick	☐ Concrete ☐ Concrete Block ☐
2. Wall Structure	
a. Wood Frame: Post & Bea	m Balloon
	Brick Stone Concrete
Concrete Block□	prior profite ConcreteC
c. Iron d. Steel e.	Oth became
3. Wall covering: Clapboard	Board & Batten Wood Shingle
Shipiap Novelty Li Asb	estos Shingle 🗌 Sheet Metal 🗍 👤
	le 🗌 Brick Veneer 🗌 Stone Veneer 🗍
Bonding Pattern:	Other:
4. Roof Structure	
a. Truss: Wood Iron	Steel Concrete
b. Other:	
5. Roof Covering: Slate Wo	od Shingle Asphalt Shingle
Sheet Metal Built Up	Rolled Tile Other:
6. Engineering Structure:	
7. Other:	
Appendages: Porches Towers C	upolas Dormers Chimneys
Sheds Ells Wings Bay Win	
Roof Style: Gable Hip Shed	Flat Mansard Gambrel
Jerkinhead Saw Tooth With M	onitor With Bellcast
With Parapet With False Front	
Number of Stories: 2	a Other.
Number of Payer	Walisanaa Taashaan
Number of Bays: 4	Entrance Location:sides
Approximate Dimensions:	
	Brook American
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat Zoning Roads	Positive Negative
Development□ Deterioration□	Mixed Other:
Alteration ☐ Other:	2000 2000

|SURVEY NUMBER:

NEGATIVE FILE NUMBER:

ADDITIONAL ARCHITECTURAL OR STRUCTURA	AL DESCRIPTION:
Massing - Squarish block with clapboarded selevations. Each wing rises to a hipped ro	ide wings on north and south of with dormer. Enclosed side
porches. Fenestration - 2/2 sash. Plain surround. Entrances - Side. Undistinguished because Enrichments - Paired brackets with drops at	of rennovation and updating. cornice.
RELATED STRUCTURES: (Describe)	
STATEMENT OF SIGNIFICANCE:	
This building is similar to other Ita and makes a significant contribution to the Johnson St. It was probably built in 1889 tenements on this side of the street were Alfred Lister, an employee of the Crystal Jackson, a paper hanger.	e scale and massing of houses on the year that the other large erected. The tenants in 1901 were
REFERENCES: 1890, Sanborn maps; directories,	
MAP: (Indicate North in Circle)	SURROUNDING ENVIRONMENT: Open Land Woodland
	Scattered Buildings Moderately Built Up Densely Built Up Residential Commercial Agricultural Industrial
	Roadside Strip Development[] Other:
	RECORDED BY: C. Richard Morsbach ORGANIZATION:
	VT. Div. for Historic Preservation DATE RECORDED: 6/28/78



	NEGATIVE FILE NUMBER:
OF VERMONT	UTM REFERENCES:
ion for Historic Preservation	Zone/Easting/Northing
Montpelier, VT 05602	
그 경기에 하는 어린 사람들은 그는 사람들 살아왔다.	
HISTORIC SITES & STRUCTURES SURVEY	U.S.G.S. QUAD. MAP:
Individual Structure Survey Form	
	PRESENT FORMAL NAME:
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington	
LOCATION:	PRESENT USE: apartment
17-19 Johnson St.	ORIGINAL USE: apartment
	ARCHITECT/ENGINEER:
COMMON NAME:	
	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: dwelling	
OWNER: Patrick T. Brown	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS:	Excellent Good
	Fair Poor
ACCESSIBILITY TO PUBLIC:	
Yes No Restricted	STYLE: Italianate
LEVEL OF SIGNIFICANCE:	STYLE: Italianate DATE BUILT:
Local State National	
GENERAL DESCRIPTION:	c. 1889
Structural System	
Structural System	☐ Concrete ☐ Concrete Block ☐
	□ concrete □ concrete Block□
2. Wall Structure	
a. Wood Frame: Post & Bea	
	Brick Stone Concrete
Concrete Block	
c. Iron□ d. Steel□ e.	
3. Wall Covering: Clapboard	Board & Batten Wood Shingle
	estos Shingle 🗌 Sheet Metal 🗍
	le 🗌 Brick Veneer 🗍 Stone Veneer
Bonding Pattern:	Other:
4. Roof Structure	
a. Truss: Wood Iron	Steel Concrete
b. Other:	
5. Roof Covering: Slate Wo	od Shingle Asphalt Shingle
Sheet Metal Built Up	Rolled Tile Other:
6. Engineering Structure:	
7. Other:	
Appendages: Porches Towers C	upolas Dormers Chimneys
Sheds	dow∏ Other:
Roof Style: Gable Hip Shed	
Jerkinhead□ Saw Tooth□ With M	
With Parapet With False Front	1 Other:
Number of Stories: 2	
Number of Bays: 5	Entrance Location: center
Approximate Dimensions:	Entrance Location:center
habbrowing contratous.	
THREAT TO STRUCTURE:	LOCAL ATTITUDES:
No Threat Zoning Roads	
Development Deterioration	Positive Negative
	Mixed Other:
Alteration Other:	

SURVEY NUMBER:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:		
Massing - Square block with rear wings. 2 first floor. Shed roof on north elevation Fenestration - 1/1 sash. Architrave has w Entrance - Center, cornice strip on top of Enrichments - Turned posts on porch. Pair	with dormer. ood cornice strip. architrave door missing.	
RELATED STRUCTURES: (Describe)		
RELATED STRUCTURES: (Describe)		
STATEMENT OF SIGNIFICANCE:		
Johnson St. It was probably built c. 1889 large tenements on Johnson St., probably f truckman who lived nearby on Murray St. I workers who needed to be abel to walk to w waterfront. The tenants in 1901 were Geor Burlington, and William Lee, a lumber sale	or (or perhaps by) J. Levee, a t was intended to house industrial ork either downtown or on the ge Allen, a porter at the Hotel	
REFERENCES:		
1890, Sanborn maps; directories.		
MAP: (Indicate North in Circle)	SURROUNDING ENVIRONMENT: Open Land Woodland Scattered Buildings Moderately Built Up Densely Built Up Residential Commercial Agricultural Industrial Roadside Strip Development Other:	
	RECORDED BY: C. Richard Morsbach ORGANIZATION: VT. Div. for Historic Preservation DATE RECORDED:	

6/28/78