MECHANICS LANE

The state of the s	SURVEY NUMBER:
	Mechanics La
	NEGATIVE FILE NUMBER:
	UTM REFERENCES:
Montpelier, VT 05602	Zone/Easting/Northing
HISTORIC SITES & STRUCTURES SURVEY Individual Structure Survey Form	U.S.G.S. QUAD. MAP:
	PRESENT FORMAL NAME: G. Scatchard Ltd. Pottery
COUNTY: Chittenden	ORIGINAL FORMAL NAME:
TOWN: Burlington LOCATION:	DDECEME HCE.
	PRESENT USE: commercial ORIGINAL USE:
Mechanics La East side 127 S. Winooski	ARCHITECT/ENGINEER:
COMMON NAME:	
FIINCTIONAL TYPE.	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: commercial OWNER: Burlington Free Press	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: College Street	Excellent Good
	Fair Poor 🗆
ACCESSIBILITY TO PUBLIC:	THEME:
Yes No Restricted	STYLE: Queen Anne commercial
LEVEL OF SIGNIFICANCE: Local State National	DATE BUILT: ca. 1892
GENERAL DESCRIPTION:	Ca. 1072
Structural System	
	Concrete Concrete Block
2. Wall Structure	
a. Wood Frame: Post & Bea	
	Brick Stone Concrete
Concrete Block	a Othora
c. Iron d. Steel 3. Wall Covering: Clapboard	e. Other:] Board & Batten [] Wood Shingle[]
	Stucco Sheet Metal Aluminum
	Veneer ☐ Stone Veneer ☐
Bonding Pattern: American	Other:
4. Roof Structure	
· · · · · · · · · · · · · · · · · · ·	Steel Concrete
b. Other: 5 Roof Covering: Slate D. N	Wood Shingle [] Asphalt Shingle []
Sheet Metal Built Up	Wood Shingle
6. Engineering Structure:	
7. Other:	
Appendages: Porches Towers	Cupolas Dormers Chimneys
Sheds Ells Wings Ot	ner:
Jerkinhead Saw Tooth Wit	d Flat Mansard Gambrel Monitor With Bellcast
With Parapet With False From	
Number of Stories: 2	hand .
Number of Bays: 3 x 8	Entrance Location: center
Approximate Dimensions:	Lettle Later Commence
munnam mo empuemunna	!LOCAL ATTITUDES:
THREAT TO STRUCTURE: No Threat	WE FALSE AND L. AND THE POST OF THE PROPERTY OF THE PARTY
Development Deterioration	Positive Negative

ADDITIONAL APCHITECTURAL OR STRUCTURAL DESCRIPTION:		
Rectangular block. Double windows on sash. Entrance - new aluminum frame door		
cornice with diagonal faced bricks in frieze area. Building adjoins the free press building.		
•		
	·	
•		
	·	
RELATED STRUCTURES: (Describe)	~~ ~	
,,		
	·	
STATEMENT OF SIGNIFICANCE:	.	
This brick structure was used primaril		
stable around the corner on Markham's Lane.		
a similar structure which operated as a Hay		
was built in ca. 1892 for the same purpose.		
renovated and used for commercial activity.	. It is the rear of 125 So. Winooski	
Ave.		
REFERENCES:		
MAP: (Indicate North In Circle)	SURROUNDING ENVIRONMENT:	
(3.1.2.3.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	Open Land Woodland	
	Scattered Buildings	
	Moderately Built Up	
	Densely Built Up	
	Residential Commercial	
	Agricultural Industrial	
	Roadside Strip Development	
	Other:	
·	·	
	RECORDED BY:	
	Adele Cramer	
	ORGANIZATION:	
	VT Division for Historic Preservation	
	DATE RECORDED:	
	12/20/77	